



Transport Canada Civil Aviation  
Standards Branch (AART)  
330 Sparks Street  
Ottawa, ON, Canada  
K1A 0N5

Company File: 5015-19034  
RDIMS: 16969876

Date: October 28, 2020

Mr. Eric Lee Chan Wai  
Airfoil Services Sdn Bhd  
No.12, Jalan Teknologi  
Taman Sains Selangor 1  
Kota Damansara PJU5  
47810 Petaling Jaya  
Selangor  
Malaysia

**Subject: Authorization of FAA-certificated Repair Stations located outside the United States**

Dear Mr. Eric Lee Chan Wai,

This letter authorizes **Airfoil Services Sdn Bhd** Certification No. **A6FY344J** to perform maintenance and modifications on aeronautical products, excluding aircraft, under TCCA regulatory control pursuant to Section B, Paragraph 4.0, of the FAA/TCCA Maintenance Implementation Procedures (MIP).

This authorization is limited to **V2500 engines** manufactured by **IAE International Aero Engines**, **CF6-80C2 engines** manufactured by **General Electric**, **CFM56-3/5A/5B/(5B/P)/5C/7B engines** manufactured by **CFM International**, and the work performed must be within the ratings and limitations contained in your 14 CFR Part 145 certificate, operations specifications and applicable capability lists dated **July 29, 2020 Rev. 0**. Any changes applied to your certificate, operations specifications, or capability list will invalidate this authorization and a new authorization request will be required by TCCA.

This TCCA authorization shall remain in effect until **Airfoil Services Sdn Bhd** FAA Repair Station Certificate expires **October 31, 2021** or if the Certificate has been surrendered, suspended or revoked. In order to renew this authorization, TCCA requires **Airfoil Services Sdn Bhd** to provide their renewed certificate, and demonstrate compliance with the MIP Section B, Paragraph 4.1, as part of their new authorization request.

Regards,

Marc Pichette  
Civil Aviation Safety Inspector  
Operational Airworthiness, Standards